Odd Fellows Cemetery Gate
East side of Route 13, approximately .2 mile
north of junction with Route 12
Smyrna
Kent County
Delaware

HABS DEL, I-SMYR, 8-

HABS No. DE-237

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS DEL, I-SMYR, B-

ARCHITECTURAL DATA FORM

| TATE | COUNTY | TOWN OR VICINITY | |
|---|-----------------------------------|--|--------------------|
| Delaware | Kent | Smyrna | |
| HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Odd Fellows Cemetery Gate | | | HABS NO. DE-237 |
| SECONDARY OR COMMON NAMES OF S | TRUCTURE | | · |
| COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) East side of Route 13, approximately .2 mile north of junction with Route 12 | | | |
| DATE OF CONSTRUCTION (INCLUDE SOURCE) 1864 (Smyrna Odd Fellows Organization) Unknown | | | |
| SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The Odd Fellows Cemetery Gate in Smyrna is believed to be the last surviving Odd Fellows cemetery gate on the east coast. | | | |
| STYLE (IF APPROPRIATE) | | | |
| MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Wood frame | | | |
| HAPE AND DIMENSIONS OF STRUCTU | RE (SKETCHED FLOOR PLANS ON SEPAF | RATE PAGES ARE A | ACCEPTABLE) |
| EXTERIOR FEATURES OF NOTE | | | |
| The gate consists of a semicircular arch springing from chamfered posts, abutting wings at the height of the posts, and swinging gates which are constructed of chamfered verticals set in a frame with a curved upper profile. A sawn wood decora- | | | |
| INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) tive piece is mounted or of the arch and an over- three-link chain hangs for center of the underside. | | and an over-size, nain hangs from the | |
| MAJOR ALTERATIONS AND ADDITIONS | SWITH DATES | | |
| The gate was restored to its original appearance in 1983-84. | | | |
| PRESENT CONDITION AND USE Excellent condition; gate | | | |
| OTHER INFORMATION AS APPROPRIATE | | | |
| | | | |
| SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) | | | |
| COMPILER, AFFILIATION Center for Historic Archi of Delaware | itecture and Engineering, Unive | ersity DA ⁻ | TE pril 1986 |